



Позиция	Количество	Номер для заказа	Описание	PG
2	7	141113180	Self-tap. fill. h. screw	11
4	1	316051260	Gear-box compl. Quick	47
6	2	141119850	Fillister head screw	11
8	1	317004160	Motor, 18 V (LT)	43
9	1	316050450	Switch slide compl.	12
10	1	343431110	Housing w.cover	26
11	1	342021670	Spring clip	11
12	1	343430890	Switch slide,R/L	11
14	1	343397990	Pressure plate	11
15	1	343394790	Switch slide	11
16	1	343410630	Switch	30
17	1	338058370	Rating plate	11
25	1	143160080	Toroidal Ferrite OD11.5*ID5*9	13
26	1	343083380	LED lense	13
27	1	339137270	Hook	13
30	1	343448690	bit-depot 18 V	13
95	1	343439680	Cover cap	11
850	1	627240000	Патрон Futuro Plus S2M 13мм с Quick	
1001	1	338504870	Wiring diagram	

